

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-370

1. Name		
Present Past Other Name (if any):	: Chhatri : :	
2. Location		
LONGITUDE 75°31' E	LATITUDE 27 ^o 42' N	
Address	: Near Masjid bus stand, S	Salumbar
	: Village (village code)	Salumbar.
	Post: Salumbar State: Rajasthan	District: Udaipur PIN: 313027
Approach district/		at salumbar in Udaipur District. Jdaipur bus stands. It is well s services.
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple Mosque Minar Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) <i>Chhatri</i>
Engineering structure Bridge Tunnel Other engineering structure	<u>structures</u> h	lote: It is a canopied chhatri aving a dome. The chhatri rest n carved pillars.

4. Property Use

ABANDONED√ / IN USE Present Memorial 2 Past Memorial : 5. Age (Source) PERIOD 19thCentury AD : YEARS 2 **Precise date of Construction** 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 5 Any other (Please specify) : Name 2 Address : Phone : 7. Association • WITH EVENTS In History 2 In Rituals : In Building Construction 2 Any other (specify) 2

WITH PERSONS • Patron **Architect / Engineer** Any other (specify)

8. Statement of Significance

 Architectural	Canopied Chhatri having a dome.
Archaeological	
Historical	
Religious	
Any other (specify)	:

1

:

:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
* Drawings (Attach extra sheet if necessary) Rural settings Stand in Isolation Integral part of a Landscape / Street / Complex		
: (m / cm/ feet / inch)		
The Chhatri is oriented East/West and faces the East.		
The Chhatri has carved pillars.		

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques Material of Construction		Trabeate system Stone, brick etc.

11. Condition Assessment

In General

Good√/ Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discolouration, Cracks, blackening, stains, deposition of soot, vegetational growth etc.

12. Threats to the Property

	Natural
\checkmark	Negligence
\checkmark	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS