



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-395

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Gateway  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75°31'E

**LATITUDE** 27°42'N

#### Address

Maharana pratap Chhatri Gate, Chawand.

: **Village (village code)** Chhawand  
**Post:** Chawand **District:** Udaipur  
**State:** Rajasthan **PIN:** 313904

**Approach district** : The Gateway is situated at Chawand in Udaipur District. It is 52km away from Udaipur bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a gateway which has battlemented parapet. There is a painting of Maharana pratap at either side of the gateway. The adjacent walls at either side of the gateway, rod crosses. The walls are not plastered.

#### 4. Property Use

---

**ABANDONED√ / IN USE**

**Present** : Gateway  
**Past** : Gateway

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> Century AD.  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

**scenic landscape.**

<input checked="" type="checkbox"/>	Architectural	Gateway having battlemented parapet.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban** ✓ / **Rural Setting**  
**Surroundings**
    - \* **Drawings** (Attach extra sheet if necessary)  
Rural setting
    - Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
  - **Quantification**  
Area Dimension ( L x B x H) :  
(m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
  
  - **Spatial Organization**  
Orientation : The Gateway is oriented North/South and faces the South.  
Plan :  
Allocation of Spaces :
- ARCHITECTURAL STYLE**
- **Ornamentation**  
Exteriors : It is a gateway having parapet.  
Interiors :  
Movable Collections :
- Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Trabeate system
- Material of Construction** : Brick, stone

## 11. Condition Assessment

---

In General

Good  / Fair  good

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):** blackening and vegetation growth.

Pilling of plaster and blackening, vegetation growth ,

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**