

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/UDP-404 **SECTION I: IDENTIFICATION** 1. Name Present Jain Mandir Past Other Name (if any): 2. Location LONGITUDE 75°31' E **LATITUDE** 27°42'N **Address** Ramnath Mandir Jawar, Udaipur Village (village code) Jawar Post: Tidi **District:** Udaipur State: Rajasthan **PIN: 313801 Approach** The Temple is situated at Jawar in Udaipur District. It is 32km away from bus stand Udaipur. It is well connected by regular bus services. 3. Property Type Buildings Religious structures **Other Structures** Palace Temple Wall Fort Mosque Gateway Minar Citadel Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is a temple which is in structures ruined state. Fallen and damaged Public square architectural parts are scattered all Bridge around. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use		
	ABANDONED / IN USE :	
Present Past	: Ruins : Religious	
5. Age (Source)		
PERIOD YEARS	: 11 th Century AD :	
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :	
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE :	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify) Name Address Phone	: : :	
7. Association		
WITH EVENTS		
In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify)	: : : :	
8. Statement of Significance		
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Decorative designs on the door lintel.	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context
 Urban / Rural Setting

Surroundings

* **Drawings (**Attach extra sheet if necessary)

Rural Setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

Spatial Organization

Orientation : The Temple is oriented East/West and faces the East.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The Temple has decorative pattern on the door lintel.

Interiors

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Nagara style of temple.

Building Techniques : Trabeate system.

Material of Construction : Stone.

11. Condition Assessment	
In General	Good / Fair Good
	√ Sign of DeteriorationSerious DeteriorationDanger of Disappearance
Note – Plaster is peeling off.	
In Brief (Attach extra sheet i	f necessary):
Dilapidated.	
12. Threats to the Property	
	 √ Natural √ Negligence ✓ Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS