

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS 11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments		
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/UDP-409
Present Past Other Name (if any): 2. Location	: Panch lingi Mahadev M : :	andir
LONGITUDE 75°31'E	LATITUDE 27°42'N	
Address	Shree Mahasatya, Gangu k	Kund, Main road Aaid, Udaipur
	: Village (village code)	
	Post: Udaipur State: Rajasthan	District: Udaipur PIN: 313001
Approach	Udaipur district. It is	d near Gangu Kund at Aaid in 3km away from, Udaipur bus ed by regular bus services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures	Other Structures Wall Gateway Pillar Others (specify)-
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard	Note: It is small temple dedicated to lord Shiva. The temple has five Shiva-linga placed in a separate room. Door-lintel of the main Shrine is carved with floral designs.

4. Property Use

ABANDONED / IN USE: In use

Present Past	: Religious: Religious		
5. Age (Source)			
PERIOD YEARS	: 18 th Century AD		
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection			
	SINGLE /MULTIPLE :		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:		
Private	:		
Any other (Please specify) Name			
Name Address	: :		
Phone			
7. Association			
WITH EVENTS			
In History	:		
In Rituals			
In Building Construction	÷		
Any other (specify) • WITH PERSONS	•		
Patron			
Architect / Engineer	•		
Any other (specify)			
, (-1),			
8. Statement of Significance			
Architectural- Ornamented door-line Archaeological Historical Religious Any other (specify)	ntels and 'Dvar-Shakas'.		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context Urban √/ Rural Setting

Surroundings

* **Drawings (**Attach extra sheet if necessary)

Urban setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

Spatial Organization

Orientation : The Temple is oriented East/West and faces the East.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Floral patterns in the 'Dvar-Shakas'.

Interiors

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System
Building Techniques

Material of Construction

Indo-Persian. Masonry work.

Stone.

11. Condition Assessment		
In General	Good √/ Fair	
	√ Sign of DeteriorationSerious DeteriorationDanger of Disappearance	
In Brief (Attach extra sheet if necessary):		
Discoloration and peeling of plaster.		
12. Threats to the Property		
	√ Natural	
	√ Negligence	
	Vandalism Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
10. Addio / Video	(related to rituals / performance / festivals etc.)
Reference	,
Kelelelice	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS