

#### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/UDP-472 **SECTION I: IDENTIFICATION** 1. Name Present Statues studded in the Boundary wall **Past** Other Name (if any): 2. Location **LONGITUDE** 75°15' E LATITUDE 27° 40' N **Address** Aaid Maind Road, Jain Mand Marg, Udaipur Village (village code) Post: Udaipur **District:** Udaipur State: Rajasthan **PIN**: 313001 Approach district The Mandir is situated near Aaid in Udaipur city. It is 3km away from Udaipur bus stand. It is well connected by regular bus services 3. Property Type Religious structures **Buildings** Other Structures Palace Temple Wall Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Statues Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: There is large number of statues of old Jain temple has structures been studded in the wall. The Bridge Public square Park or garden images are medallions and are Tunnel master pieces of their own time. Other engineering structure Graveyard The majority of the images are of Baolis, Well celestial women and heliographs Tank (Vyalas). The figures of these Cave mythical figures are of very good

quality.

4. Property Use			
		ABANDONED / IN USE√	
Present Past	:	Religious	
5. Age (Source)			
PERIOD YEARS	:	17 <sup>th</sup> Century AD	
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : :		
6. Ownership / Level of Protection			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	: : : : : : : : : : : : : : : : : : : :	SINGLE /MULTIPLE :	
WITH EVENTS     In History     In Rituals     ✓ In Building Construction     Any other (specify)     WITH PERSONS     Patron     Architect / Engineer     Any other (specify)  8. Statement of Significance  Architectural	: : : : : : : : : : : : : : : : : : : :	Old images and relics have been studded in walls	
Archaeological  Historical			

Religious

Any other (specify) : These images and relics are parts of an old dilapidated

temple

#### **SECTION II: DESCRIPTION**

## 9. Physical Description and Decorative Features

• Context

Urban √ Rural Setting Surroundings

\* **Drawings (**Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension ( $L \times B \times H$ ):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

Spatial Organization

Orientation : The Temple is oriented East/West and faces the East

Plan

Allocation of Spaces :

**ARCHITECTURAL STYLE** 

Ornamentation

Exteriors : Women figures in different form and design

Interiors : It has very good number of dismembered sections of

temples and divine images

Movable Collections

**Any Other** (specify) : Ritual objects – Ceremonial objects

10. Construction Technology

Structural System : Trabeate system

**Building Techniques** : Sculpted Three and two dimensional images

**Material of Construction** : Stone masonry, marble

11. Condition Assessmen	nt		
In General	Good / Fair √		
	Sign of Deterioration  ✓ Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet if necessary):			
Well maintained			
12. Threats to the Proper	ty		
	<ul> <li>√ Natural</li> <li>√ Negligence</li> <li>✓ Vandalism</li> <li>Urban Pressures</li> </ul>		

# **SECTION III:** REFERENCES

# 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
	NAME
NAME	NAME
COMMENTS	COMMENTS