

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/Udp-475 **SECTION I: IDENTIFICATION** 1. Name **Present** Shiv Lingam Past Other Name (if any): 2. Location **LONGITUDE** 75°33'E LATITUDE 27°42'N **Address** Ganyu Kund Main Road Aid, Udaipur Village (village code) Post: Udaipur **District:** Udaipur State: Rajasthan **PIN:** 313001 The Ling is situated at Gangu Kund, in Udaipur city. It Approach is 3km away from Udaipur bus stand. It is well connected by regular bus service. 3. Property Type Religious structures **Other Structures Buildings** Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is old Shiva temple with ample of archaeological relics structures studded in the walls of the Bridge Public square renovated shrine. The door lintel Park or garden Tunnel and dvar-sakha has beautiful Other engineering structure Graveyard ornated images. Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE√
Present	: Delinious
Past	Religious : Religious
5. Age (Source)	
PERIOD	: 18 th Century AD
YEARS	:
Precise date of	:
Construction	
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)state Govt.	
Private	:
Any other (Please specify)	:
Name	:
Address	
Phone	
7. Association	
WITH EVENTS	
In History	:
√ In Rituals	:
In Building Construction	:
Any other (specify)	:
 WITH PERSONS 	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	Old shrine of lord Shiva with beautiful ancient images
√ Archaeological	
Historical	
Religious Any other (specify)	
Any other (specify)	•

SECTION II: DESCRIPTION

9.	Physical Description and De	ecora	tive Features
Context Urban √/ Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban Setting
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	(III / GIII/ ICCE / IIIGII)
•	Spatial Organization Orientation	:	The Ling is oriented East/West faces the East
	Plan Allocation of Spaces	:	
•	CCHITECTURAL STYLE Ornamentation √ Exteriors √ Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Pillared verandah walls are studded with images Dismembered section of old temple
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	: : :	Nagar Temple Initially made of Trabeate system Stone
11	. Condition Assessment		
	In General G	Good	/ Fair √ Fair
		٧	Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Algae	deposition	on Shiva	Linga

12.	Threats	to the	Property

 Natural
 Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DECODIDEION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
NAIVIE	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS