



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-521

SECTION I: IDENTIFICATION

1. Name

Present : Dak Bangla
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

Address

Near Chamunda Mata Mandir, Chawand.

: **Village (village code)** Chawand

Post: Chawand

District: Udaipur

State: Rajasthan

PIN: 313904

Approach

: The Structure is situated at Chawand, in Udaipur District. It is 52km away from Udaipur bus stand,. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a beautiful masonic structure surmounted by a dome and an 'Amalaka'. The Structure is clad with rubble masonry. It is embellished with perforated windows. There is a structure having Curvilinear Shikar crowned by 'Amalakas' on either side of the main structure.

4. Property Use**ABANDONED / IN USE :** In use

Present : Residence
Past : Residence

5. Age (Source)

PERIOD : 19th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE /MULTIPLE :**

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private : P.W.D
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Architectural – Structure Surmounted by dome & an ‘Amalaka’. |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

:

11. Condition Assessment

In General

Good ✓/ Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well Maintained.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS