

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/UDP-525
Present Past Other Name (if any): 2. Location	: Amar kund : :	
LONGITUDE 75°31'E	LATITUDE 27°42'N	
Address	Chand pole , Udaipur	
	: Village (village code)	
	Post: Udaipur State: Rajasthan	District: Udaipur PIN: 313001
Approach		situated near Chand pole in away from bus stand, Udaipur. egular bus services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)- kund
Engineering structure Bridge Tunnel Other engineering structure	structures Public square	Note: It is a huge pond or kund which is surrounded by all sides. It has got elevated platform which is reached by staircase on all side. It has been fortified by long walls.

4. Property Use			
-		ABANDONED / IN USE: In use	
Present	:	Water tank	
Past	:	Water tank	
5. Age (Source)			
DEDIOD		40th Ozartumu AD	
PERIOD	:	18 th Century AD	
YEARS	•		
Precise date of Construction			
Completion	:		
Subsequent changes	•		
Destruction / Demolition			
Destruction / Demontion	•		
6. Ownership / Level of Protection			
		SINGLE /MULTIPLE :	
Bullion Arches III 100			
Public: Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	•		
Any other (Please specify)	•		
Name	:		
Address Phone	•		
Phone	•		
7. Association			
WITH EVENTS			
In History			
In Rituals			
In Building Construction	•		
Any other (specify)	•		
WITH PERSONS	•		
Patron			
Architect / Engineer			
Any other (specify)	:		
Any other (opeony)	•		
0.04-444			
8. Statement of Significance			
Architectural			
Archaeological			
Historical			
Religious			
√ Any other (specify)	: Ku	nd has been used for public use.	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context Urban √/ Rural Setting

Surroundings

* **Drawings (**Attach extra sheet if necessary)

setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys

Spatial Organization

Orientation : The kund is oriented east-west and faces the east.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Bridge has been constructed with multifoliated arch

style.

Interiors

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Bridge has been constricted arcuate style.

Building Techniques : Arcuate system.

Material of Construction : Bricks & stone

11. Condition Assessm	nent
In General	Good √/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra s	sheet if necessary): Yes there is algae formation not only on structure
arched based but also in	the pound.
12. Threats to the Prop	erty
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
=:0:0:0	
NAME	NAME
18. Reviewers	
NAME	NAME
	1.07 117100
COMMENTS	COMMENTS