



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-541

SECTION I: IDENTIFICATION

1. Name

Present : Girwal Pol
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

Address

Girwal Pol, Bhindar.

: **Village (village code)** Bhindar

Post: Bhindar

District: Udaipur

State: Rajasthan

PIN: 313603

Approach

: The Gateway is situated at Bhindar in Udaipur District. It is 70km away from Udaipur bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a gateway having foliated arch opening. It has battlemented parapet. Arch has medallions on the Spandrel.

4. Property Use**ABANDONED / IN USE** ✓

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 17th Century AD.
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE / MULTIPLE :**

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Arch has medallions on the spandrel.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input checked="" type="checkbox"/>	Any other (specify)	: Entrance Gate.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings

* **Drawings** (Attach extra sheet if necessary)

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 02

Number of Storys : 01

- **Spatial Organization**

Orientation : The Gateway is oriented North/South and faces the South.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors : Foliated arch opening battlemented parapet.

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Indo- Islamic.


Building Techniques : Arcuate System.

Material of Construction : Stone, plaster.

11. Condition Assessment

In General

Good / Fair



Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of Plaster and Blacking of the surface.

12. Threats to the Property

√	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS