



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/UDP-559

### SECTION I: IDENTIFICATION

#### 1. Name

Present : Mahrajao ki Chhatri  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75°31'E

LATITUDE 27°42'N

#### Address

Gangu Kund, Main road Aaid, Udaipur

: **Village (village code)**

**Post:** Udaipur

**District:** Udaipur

**State:** Rajasthan

**PIN:** 313001

#### Approach

: The Chhatri is situated near Gangu Kund at Aaid in Udaipur District. It is 3km away from, Udaipur bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)- Chhatri

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a canopied Chhatri having angular ornamented pillars. The Chhatri stands on a raised platform. The dome is clad with lime-plaster.

---

**4. Property Use****ABANDONED / IN USE :** Abandoned

**Present** : Memorial  
**Past** : Memorial

---

**5. Age (Source)**

**PERIOD** : 18<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection****SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)

**Private** : Eklingiji trust, city palace, Udaipur  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

---

**7. Association**

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** : It is related to sarcophagus tradition.
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

---

**8. Statement of Significance**

- |                                     |                                                      |
|-------------------------------------|------------------------------------------------------|
| <input checked="" type="checkbox"/> | Architectural- Canopied Chhatri having bulbous dome. |
| <input type="checkbox"/>            | Archaeological                                       |
| <input type="checkbox"/>            | Historical                                           |
| <input type="checkbox"/>            | Religious                                            |
| <input type="checkbox"/>            | Any other (specify)                                  |

:

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban ✓ / Rural Setting**  
**Surroundings**  
**\* Drawings (Attach extra sheet if necessary)**  
Urban setting  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  
(m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Chhatri is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Dome is clad with lime-plaster.  
Interiors :  
Movable Collections :  
**Any Other (specify)** :

### 10. Construction Technology

---

- |                                 |                    |
|---------------------------------|--------------------|
| <b>Structural System</b>        | Indo-Persian.      |
| <b>Building Techniques</b>      | Arcuate system.    |
| <b>Material of Construction</b> | Stone and plaster. |

## 11. Condition Assessment

---

In General

Good ✓/ Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Discoloration and vegetational growth.

---

## 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

Udaipur Sambhag ka Jilewar Sanskritik and Aetihasic Ahtyayan, Dr. Mohan Lal Gupta, 2009, Rajasthani Granthagar, Jodhpur

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**