螹

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001 www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites/Monuments

Serial No.: sd01bj0001

	<u>SECTION I</u> : IDENTIFICATION	I
1.Name		
Present	Bastion, where a wall of Jahan Pa Pithora Fort	nnah meets the wall of Rai
Past		
Other Name (if any)		
2. Location		
Address	LONGITUDE 77°12' E LATTITU Adchini	DE 28°31'N
Approach	Village (village code) District State Delhi PIN 110	South Delhi
3.Property Type		
Buildings Palace Gort Gitadel Govt. building Railway station Defence building Industrial building Residential buildi Engineering structure Bridge Tunnel Other engineering structure	lings ng Open space and related structures Public square Park or garden Graveyard	Other Structures ✓ Wall □ Gateway □ Pillar □ Others (specify)

4.Property Use		
D	D 4 4 134 4	ABANDONED / IN USE
Present Past	Protected Monument Fortification of the city	
5. Age (Source)		
PERIOD YEARS		
Precise date of Construction Completion Subsequent c Destruction /		
6. Ownership /	Level of Protection	
		SINGLE /MULTIPLE
Public	Archaeological Survey of	India
Private		
Any other (Pl	ease specify)	
Name Address		
Phone		
7. Association		
• WITH I		
	In History In Rituals In Building Constructi Any other (specify)	on
•WITH P	PERSONS	
	Patron	
	Architect / Engineer Any other (specify)	
8. Statement of S		
	, c c	
	Archaeological Historical	
	Religious	
	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description a	nd Decorative Features	
• Context	* Drawings (Attach extra sheet if necessary)	
Urban / Rural Setting Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
• Quantification Area Dimension (L x	B x H)	
Number of Blocks Number of Storys	(m / cm/ feet / inch)	
• Spatial Organization Orientation		
Plan		
Allocation of Spaces		
•		
ARCHITECTURAL ST	<u> TLE</u>	
• Ornamentation Exteriors		
Interiors		
Movable Collections		
Any Other (specify)		
10. Construction Techno	logv	
Structural System	The rampart of are 5-6 m in thickness and their extant height goes as high as 18m and at places a moat runs on its outer sides. Hauz Rani is one of the three extant galias of quila Rai	
Building Techniques	<u>Pithora.</u>	
Material of Construc	tion	

11. Condition Assessment			
In General	Good / I	Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if no	ecessary)		
12.Threats to the Property			
	_ _ _	Natural Negligence Vandalism Urban Pressures	

SECTION III: REFERENCES

13. **Reference Sources** (published and unpublished textual details)

Inventory of monuments and sites of national Importance volume 1 part 3, ASI

14. Photographs		_
Photo Reference	(attach list as in page 6, in case of multiple photographs)	
CAPTION		
15. Audio / Video		
(rela Reference	ted to rituals / performance / festivals etc.)	
DESCRIPTION		
16. Maps/Plans/Draw	ings	
17. Listers		
NAME: Ankita Vats NAME: Bharti Pando NAME: Tripta Sharn	·	
18.Reviewers		
NAME	NAME	
COMMENTS	COMMENTS	