## 瞴

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001 <u>www.ignca.gov.in</u>

## **Documentation format for Archaeological and Heritage Sites/Monuments**

Serial No.: sd109bk0001

Name			
Present	Tomb of Bhure Khan		
Past			
Other Name (if any)			
2. Location			
Address	D Block South Extension Village (village code)	LATTITUDE 28°34'N on- I  _ District	
		PIN	
Approach South-east of Bare Khan ka gumbad.			
3.Property Type		n na gumbau.	
	Religious structure  □ Temple □ Mosque □ Minar □ Church □ Monastery □ Stupa ✓ Tomb, Mausdings	es Other Structures Wall Gateway Pillar Others (specify) soleum	

Present	Protected monument				
Past	Tomb				
5. Age (Source)					
PERIOD YEARS					
Precise date of Construction I Completion Subsequent ch Destruction / I					
6. Ownership / I	Level of Protection SINGLE /MUL	TIPLE			
Public	Archaeological Survey of India				
Private					
Any other (Ple	lease specify)				
Name Address					
Phone					
7. Association					
• WITH <b>E</b> •WITH <b>P</b>	In History In Rituals In Building Construction Any other (specify) PERSONS Patron Architect / Engineer Any other (specify)				
8. Statement of Significance					
<b>√</b>	Archaeological Historical				

9.	Physical Description a	and Decorative Features
•	Context	* <b>Drawings</b> (Attach extra sheet if necessary)
	Urban / Rural Setting Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex
• (	<b>Quantification</b> Area Dimension ( L x	( B x H)
	Number of Blocks Number of Storys	(m / cm/ feet / inch)
• §	Spatial Organization Orientation	
	Plan	Square in plan
	Allocation of Spaces	The tomb measures only 8.2 sq m.
A	RCHITECTURAL S	<u>TYLE</u>
• (	Ornamentation Exteriors	Originally it was ornamented with a band of pale blue tiles surmounted by a dome, with arched openings on the eastern,northern and southern side The western wall of monument accommodates a mihrab.
	Interiors	
	Movable Collections	
	Any Other (specify)	
10	. Construction Techno	ology
	Structural System	The tomb, much smaller than the adjacent two buildings, measures only 8.2 square meteres and lacks much of the ornamentation of the other two buildings. The staircase leading the plinth has mostly disappeared.
	<b>Building Techniques</b>	s Stone masonry
	Material of Constru	ction Walls: Random rubble masonry, Floor: stone Domed Roof: Stone
11.	. Condition Assessme	nt

In General	Good / 1	Fair				
		Sign of Deterioration				
✓		Serious Deterioration				
		Danger of Disappearance				
In Brief (Attach extra sheet if necessary) Serious deterioration: To the north of the tomb some land has been encroached upon.						
12.Threats to the Pro	perty					
✓		Natural				
		Negligence				
		Vandalism				
		Urban Pressures				

## **SECTION III: REFERENCES**

13. <b>Reference Sources</b> (published and unpublished textual details)					
1. Inventory of monuments and sites of national importance Volume I Part 3- ASI 2. Delhi The Built Heritage: A listing INTACH					
14. Photographs					
Photo Reference	(attach list as in page 6, in case of multiple	e photographs)			
CAPTION					
15. Audio / Video					
	d to rituals / performance / festivals etc.)				
Reference					
DESCRIPTION					
16. Maps/Plans/Drawing	<b>PS</b>				
	2-				
17. Listers					
17. Listers					
NAME: ANKITA VATS					
NAME: BHARTI PANI NAME: TRIPTA SHAR					
18.Reviewers					
NAME	NAME				

COMMENTS\_\_\_\_\_

COMMENTS \_\_\_\_\_