垂

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001 www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites/Monuments

Serial No.: <u>sd169w0001</u>

SECTION I: IDENTIFICATION							
1.Name							
Present	Delhi Gate (Red fort)						
Past							
Other Name (if any)							
2. Location							
Address	LONGITUDE 77° 14' E LATTITUDE 28° 29' N At the Intersection of Asaf Ali Road and Netaji Subhash Marg Village (village code) Post District Central Delhi State Delhi PIN 110006						
Approach							
3.Property Type							
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Cher public building Residential building Bridge Tunnel Other engineering structure		Other Structures Wall Gateway Others (specify)					

4.Property Use	e			
D	ABANDONED / IN USE			
Present <u>N</u>	<u>Monument</u>			
Past C	City Gate			
5. Age (Source				
PERIOD YEARS				
Completion Subsequent				
6. Ownership	/ Level of Protection			
	SINGLE /MULTIPLE			
Public	Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)			
Private				
Any other (Please specify)			
Name Address				
Phone				
7. Association				
• WITH	I EVENTS			
	In History In Rituals In Building Construction Any other (specify)			
•WITH PERSONS				
	Patron Architect / Engineer Any other (specify)			
8. Statement o	f Significance			
	□ Architectural			
	□ Archaeological□ Historical□ Religious			
	Any other (specify) This is one of four surviving gateways of Shahjahanabad of which there were originally 14.			

SECTION II: DESCRIPTION

Context	* Drawings (Attach extra sheet if necessary)
Urban / Rural Setting Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex
• Quantification Area Dimension (L x B x H)	
Number of Blocks Number of Storys	(m / cm/ feet / inch)
• Spatial Organization Orientation	
Plan	
Allocation of Spaces	
ARCHITECTURAL STYLE	
• Ornamentation Exteriors Interiors	
Movable Collections	
Any Other (specify)	
10. Construction Technology	
on either end with bastions and Building Techniques Rubble	eway is entered through a pointed arch opening flanked d similar to Turkman Gate in some respects. e masonry Valls: Rubble masonry, Domes Roof: Rubble Masonry
11. Condition Assessment	
In General (Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet if nece	essary)

12.Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference So	ources (publish	ed and unpu	blished textual details)	
1 Inventory of M	onuments and	Sites of Natio	onal Importance, ASI	
2. Delhi The Bui				
2. Denn The Bur	n Hemage. A 1	asing, mac		
14. Photographs	S			
Photo Reference	(attacl	n list as in pa	e photographs)	
CAPTION				-
				- -
15. Audio / Vide	20			
	(related to rit	uals / perforr	nance / festivals etc.)	
Reference				-
DESCRIPTION				-
				- -
16. Maps/Plans/	Drawings			
17. Listers				
NAME	Ankita Vats	NAME	Bharti Pandey	
NAME	Tripta Sharma	<u>a</u>		
18.Reviewers				
NAME			NAME	
COMMENTS			COMMENTS	